

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2349376	Test Start :	02/08/2016 @ 11:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:51
Location :	First Floor-11	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/17/2016 @ 17:00
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2349380	Test Start :	02/08/2016 @ 11:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:36
Location :	First Floor-13	Received:	02/17/2016 @ 15:23
Radon Level :	0.6 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2349382	Test Start :	02/08/2016 @ 11:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:44
Location :	First Floor-608	Received:	02/17/2016 @ 15:23
Radon Level :	0.6 pCi/L	Analyzed:	02/17/2016 @ 17:20
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2349387	Test Start :	02/08/2016 @ 11:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:27
Location :	First Floor-Girls PE Off	Received:	02/17/2016 @ 15:23
Radon Level :	4.2 pCi/L	Analyzed:	02/18/2016 @ 11:28
Error for Measurement is: $\pm$	0.7 pCi/L		

Canister ID# :	2349388	Test Start :	02/08/2016 @ 11:36
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:38
Location :	First Floor-60A-Mrs J	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/18/2016 @ 12:18
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2349389	Test Start :	02/08/2016 @ 11:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:44
Location :	First Floor-609	Received:	02/17/2016 @ 15:23
Radon Level :	0.2 pCi/L	Analyzed:	02/17/2016 @ 17:20
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2349392	Test Start :	02/08/2016 @ 11:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:52
Location :	First Floor-Lib	Received:	02/17/2016 @ 15:23
Radon Level :	0.6 pCi/L	Analyzed:	02/17/2016 @ 17:21
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2349394	Test Start :	02/08/2016 @ 11:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:17
Location :	First Floor-Copy Rm	Received:	02/17/2016 @ 15:23
Radon Level :	0.3 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2349395	Test Start :	02/08/2016 @ 12:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:02
Location :	First Floor-24	Received:	02/17/2016 @ 15:27
Radon Level :	0.2 pCi/L	Analyzed:	02/17/2016 @ 17:21
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2349396	Test Start :	02/08/2016 @ 11:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:35
Location :	First Floor-15	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 11:44
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2349404	Test Start :	02/08/2016 @ 11:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:18
Location :	First Floor-Office-530C	Received:	02/17/2016 @ 15:23
Radon Level :	1.1 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2349586	Test Start :	02/08/2016 @ 11:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:52
Location :	First Floor-Mail Rm	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 09:22
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2349588	Test Start :	02/08/2016 @ 11:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:22
Location :	First Floor-Kitchen	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2349590	Test Start :	02/08/2016 @ 11:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:32
Location :	First Floor-Art Stor	Received:	02/17/2016 @ 15:23
Radon Level :	0.5 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: $\pm$	0.7 pCi/L		

Canister ID# :	2349595	Test Start :	02/08/2016 @ 11:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:18
Location :	First Floor-Office-30A	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 12:00
Error for Measurement is: $\pm$	0.8 pCi/L		

Canister ID# :	2349597	Test Start :	02/08/2016 @ 11:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:19
Location :	First Floor-Health -31	Received:	02/17/2016 @ 15:23
Radon Level :	0.6 pCi/L	Analyzed:	02/17/2016 @ 17:21
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2349601	Test Start :	02/08/2016 @ 11:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:33
Location :	First Floor-19	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 11:44
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2349605	Test Start :	02/08/2016 @ 11:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:43
Location :	First Floor-614	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: $\pm$	0.7 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# : 2349607
Canister Type : Charcoal Canister 3 inch
Location : First Floor-21
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 02/08/2016 @ 11:31
Test Stop : 02/11/2016 @ 13:34
Received: 02/17/2016 @ 15:23
Analyzed: 02/18/2016 @ 12:00

Canister ID# : 2350061
Canister Type : Charcoal Canister 3 inch
Location : First Floor-50A Office
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 02/08/2016 @ 11:36
Test Stop : 02/11/2016 @ 13:37
Received: 02/17/2016 @ 15:23
Analyzed: 02/17/2016 @ 17:20

Canister ID# : 2355061
Canister Type : Charcoal Canister 3 inch
Location : First Floor-35B-Cust
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 02/08/2016 @ 11:11
Test Stop : 02/11/2016 @ 13:22
Received: 02/17/2016 @ 15:23
Analyzed: 02/18/2016 @ 10:20

Canister ID# : 2356583
Canister Type : Charcoal Canister 3 inch
Location : First Floor-Stage
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 02/08/2016 @ 11:12
Test Stop : 02/11/2016 @ 13:23
Received: 02/17/2016 @ 15:23
Analyzed: 02/18/2016 @ 12:18

Canister ID# : 2356587
Canister Type : Charcoal Canister 3 inch
Location : First Floor-26 Off
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 02/08/2016 @ 12:04
Test Stop : 02/11/2016 @ 14:03
Received: 02/17/2016 @ 15:27
Analyzed: 02/18/2016 @ 09:22

Canister ID# : 2360406
Canister Type : Charcoal Canister 3 inch
Location : First Floor-35B-Cust
Radon Level : 0.1 pCi/L
Error for Measurement is: $\pm$ 0.8 pCi/L

Test Start : 02/08/2016 @ 11:11
Test Stop : 02/11/2016 @ 13:22
Received: 02/17/2016 @ 15:23
Analyzed: 02/18/2016 @ 09:57

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2360419	Test Start :	02/08/2016 @ 11:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:24
Location :	First Floor-Multi-P 25/36E	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2360421	Test Start :	02/08/2016 @ 11:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:43
Location :	First Floor-611	Received:	02/17/2016 @ 15:23
Radon Level :	0.2 pCi/L	Analyzed:	02/18/2016 @ 12:18
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2360426	Test Start :	02/08/2016 @ 11:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:48
Location :	First Floor-602	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/17/2016 @ 17:21
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2362125	Test Start :	02/08/2016 @ 11:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:30
Location :	First Floor-17	Received:	02/17/2016 @ 15:23
Radon Level :	1.0 pCi/L	Analyzed:	02/18/2016 @ 12:00
Error for Measurement is: $\pm$	0.7 pCi/L		

Canister ID# :	2362898	Test Start :	02/08/2016 @ 11:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:22
Location :	First Floor-34	Received:	02/17/2016 @ 15:23
Radon Level :	0.9 pCi/L	Analyzed:	02/17/2016 @ 17:20
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2362903	Test Start :	02/08/2016 @ 11:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:35
Location :	First Floor-14	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/18/2016 @ 10:20
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2362905	Test Start :	02/08/2016 @ 11:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:46
Location :	First Floor-605	Received:	02/17/2016 @ 15:23
Radon Level :	1.0 pCi/L	Analyzed:	02/17/2016 @ 17:20
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2362911	Test Start :	02/08/2016 @ 11:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:24
Location :	First Floor-PE Off	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 12:18
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2362914	Test Start :	02/08/2016 @ 11:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:47
Location :	First Floor-603	Received:	02/17/2016 @ 15:23
Radon Level :	0.3 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2366137	Test Start :	02/08/2016 @ 11:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:33
Location :	First Floor-20	Received:	02/17/2016 @ 15:23
Radon Level :	0.5 pCi/L	Analyzed:	02/17/2016 @ 17:20
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2366138	Test Start :	02/08/2016 @ 11:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:31
Location :	First Floor-Lock/ Central Area	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 11:28
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2366141	Test Start :	02/08/2016 @ 11:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:19
Location :	First Floor-Office-31A	Received:	02/17/2016 @ 15:23
Radon Level :	0.2 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2366142	Test Start :	02/08/2016 @ 12:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:01
Location :	First Floor-Locker / Center	Received:	02/17/2016 @ 15:27
Radon Level :	0.6 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2366151	Test Start :	02/08/2016 @ 11:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:46
Location :	First Floor-607	Received:	02/17/2016 @ 15:23
Radon Level :	0.1 pCi/L	Analyzed:	02/18/2016 @ 09:22
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2366157	Test Start :	02/08/2016 @ 11:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:27
Location :	First Floor-Girls PE Off	Received:	02/17/2016 @ 15:23
Radon Level :	1.3 pCi/L	Analyzed:	02/18/2016 @ 11:44
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2366161	Test Start :	02/08/2016 @ 11:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:36
Location :	First Floor-Locker/ Central Area	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/18/2016 @ 11:44
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2366164	Test Start :	02/08/2016 @ 12:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:02
Location :	First Floor-24 Off	Received:	02/17/2016 @ 15:27
Radon Level :	0.3 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2366166	Test Start :	02/08/2016 @ 11:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:33
Location :	First Floor-20	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/18/2016 @ 11:44
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2366173	Test Start :	02/08/2016 @ 11:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:43
Location :	First Floor-611	Received:	02/17/2016 @ 15:23
Radon Level :	0.3 pCi/L	Analyzed:	02/17/2016 @ 17:21
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2366176	Test Start :	02/08/2016 @ 11:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:25
Location :	First Floor-Boys Lock Rm	Received:	02/17/2016 @ 15:23
Radon Level :	0.3 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2366177	Test Start :	02/08/2016 @ 11:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:20
Location :	First Floor-32 Faculty	Received:	02/17/2016 @ 15:23
Radon Level :	0.3 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2366178	Test Start :	02/08/2016 @ 11:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:51
Location :	First Floor-11	Received:	02/17/2016 @ 15:23
Radon Level :	0.9 pCi/L	Analyzed:	02/17/2016 @ 17:21
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2366182	Test Start :	02/08/2016 @ 11:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:17
Location :	First Floor-Main Off	Received:	02/17/2016 @ 15:23
Radon Level :	0.5 pCi/L	Analyzed:	02/17/2016 @ 17:20
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2366187	Test Start :	02/08/2016 @ 11:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:44
Location :	First Floor-610	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 09:22
Error for Measurement is: ±	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2366189	Test Start :	02/08/2016 @ 11:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:00
Location :	First Floor-1	Received:	02/17/2016 @ 15:27
Radon Level :	0.8 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2366194	Test Start :	02/08/2016 @ 11:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:28
Location :	First Floor-Girls Lock Rm 1	Received:	02/17/2016 @ 15:23
Radon Level :	0.6 pCi/L	Analyzed:	02/18/2016 @ 12:00
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2366197	Test Start :	02/08/2016 @ 11:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:30
Location :	First Floor-18	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2366198	Test Start :	02/08/2016 @ 11:36
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:37
Location :	First Floor-Office MS Blain	Received:	02/17/2016 @ 15:23
Radon Level :	1.1 pCi/L	Analyzed:	02/17/2016 @ 17:20
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2366200	Test Start :	02/08/2016 @ 11:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:51
Location :	First Floor-10	Received:	02/17/2016 @ 15:23
Radon Level :	0.7 pCi/L	Analyzed:	02/18/2016 @ 11:28
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2366456	Test Start :	02/08/2016 @ 11:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:28
Location :	First Floor-Book Rm	Received:	02/17/2016 @ 15:23
Radon Level :	0.3 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2366460	Test Start :	02/08/2016 @ 11:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:23
Location :	First Floor-Cafe	Received:	02/17/2016 @ 15:23
Radon Level :	0.6 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2367054	Test Start :	02/08/2016 @ 11:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:26
Location :	First Floor-Gym	Received:	02/17/2016 @ 15:23
Radon Level :	0.5 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2367257	Test Start :	02/08/2016 @ 11:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:21
Location :	First Floor-34A	Received:	02/17/2016 @ 15:23
Radon Level :	0.9 pCi/L	Analyzed:	02/18/2016 @ 12:00
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2367260	Test Start :	02/08/2016 @ 11:43
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:47
Location :	First Floor-604	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/17/2016 @ 17:00
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2367268	Test Start :	02/08/2016 @ 11:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:31
Location :	First Floor-16	Received:	02/17/2016 @ 15:23
Radon Level :	0.5 pCi/L	Analyzed:	02/18/2016 @ 11:44
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2367271	Test Start :	02/08/2016 @ 11:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:32
Location :	First Floor-24 Art	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 10:20
Error for Measurement is: $\pm$	0.7 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2374315	Test Start :	02/08/2016 @ 11:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:52
Location :	First Floor-Lockers/Center Area	Received:	02/17/2016 @ 15:23
Radon Level :	0.5 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2374654	Test Start :	02/08/2016 @ 11:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:21
Location :	First Floor-33	Received:	02/17/2016 @ 15:23
Radon Level :	0.5 pCi/L	Analyzed:	02/18/2016 @ 09:22
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2374655	Test Start :	02/08/2016 @ 11:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:23
Location :	First Floor-Cafe	Received:	02/17/2016 @ 15:23
Radon Level :	0.4 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2374929	Test Start :	02/08/2016 @ 11:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:26
Location :	First Floor-Gym	Received:	02/17/2016 @ 15:23
Radon Level :	0.3 pCi/L	Analyzed:	02/18/2016 @ 09:22
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2396307	Test Start :	02/08/2016 @ 12:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:03
Location :	First Floor-BL	Received:	02/17/2016 @ 15:27
Radon Level :	0.1 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: ±	0.1 pCi/L		

Canister ID# :	2396355	Test Start :	02/08/2016 @ 12:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:03
Location :	First Floor-BL	Received:	02/17/2016 @ 15:27
Radon Level :	0.5 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2396592	Test Start :	02/08/2016 @ 12:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:03
Location :	First Floor-BL	Received:	02/17/2016 @ 15:27
Radon Level :	0.1 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2396765	Test Start :	02/08/2016 @ 12:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:03
Location :	First Floor-26	Received:	02/17/2016 @ 15:27
Radon Level :	0.3 pCi/L	Analyzed:	02/18/2016 @ 11:44
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2396775	Test Start :	02/08/2016 @ 11:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:00
Location :	First Floor-1	Received:	02/17/2016 @ 15:27
Radon Level :	0.6 pCi/L	Analyzed:	02/18/2016 @ 09:22
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396796	Test Start :	02/08/2016 @ 12:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:01
Location :	First Floor-22	Received:	02/17/2016 @ 15:27
Radon Level :	0.2 pCi/L	Analyzed:	02/18/2016 @ 10:20
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2401529	Test Start :	02/08/2016 @ 12:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:03
Location :	First Floor-BL	Received:	02/17/2016 @ 15:27
Radon Level :	0.1 pCi/L	Analyzed:	02/18/2016 @ 09:22
Error for Measurement is: $\pm$	0.1 pCi/L		

Canister ID# :	2403753	Test Start :	02/08/2016 @ 12:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 14:02
Location :	First Floor-23	Received:	02/17/2016 @ 15:27
Radon Level :	0.4 pCi/L	Analyzed:	02/18/2016 @ 09:57
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 02/17/2016

Blaine Cunningham
Webster Central Schools
119 South Ave
Webster, NY 14580-

Client: Plank South Elementary
Test Location: 715 Plank Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2403760	Test Start :	02/08/2016 @ 11:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:52
Location :	First Floor-Lib	Received:	02/17/2016 @ 15:23
Radon Level :	0.6 pCi/L	Analyzed:	02/17/2016 @ 17:40
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2403797	Test Start :	02/08/2016 @ 11:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	02/11/2016 @ 13:46
Location :	First Floor-606	Received:	02/17/2016 @ 15:23
Radon Level :	0.8 pCi/L	Analyzed:	02/18/2016 @ 09:40
Error for Measurement is: $\pm$	0.7 pCi/L		

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consgrid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201