

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2396298	Test Start :	01/19/2016 @ 10:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:28
Location :	704	Received:	01/27/2016 @ 15:16
Radon Level :	0.6 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396302	Test Start :	01/19/2016 @ 10:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:37
Location :	Art Rm	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396497	Test Start :	01/19/2016 @ 11:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 14:02
Location :	BL	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: $\pm$	0.2 pCi/L		

Canister ID# :	2396812	Test Start :	01/19/2016 @ 11:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 14:02
Location :	BL	Received:	01/27/2016 @ 15:16
Radon Level :	0.6 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396884	Test Start :	01/19/2016 @ 11:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 14:02
Location :	BL	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396892	Test Start :	01/19/2016 @ 10:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:36
Location :	305	Received:	01/27/2016 @ 15:16
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2396898	Test Start :	01/19/2016 @ 10:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:50
Location :	Copy Rm	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2396907	Test Start :	01/19/2016 @ 10:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:31
Location :	708	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:22
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2396910	Test Start :	01/19/2016 @ 10:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:46
Location :	Lib	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:21
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2396916	Test Start :	01/19/2016 @ 11:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 14:02
Location :	BL	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396918	Test Start :	01/19/2016 @ 10:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:44
Location :	206	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:21
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2396921	Test Start :	01/19/2016 @ 11:12
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:55
Location :	402	Received:	01/27/2016 @ 15:16
Radon Level :	0.8 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2396928	Test Start :	01/19/2016 @ 10:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:29
Location :	711	Received:	01/27/2016 @ 15:16
Radon Level :	0.8 pCi/L	Analyzed:	01/28/2016 @ 15:07
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396936	Test Start :	01/19/2016 @ 10:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:26
Location :	Gym	Received:	01/27/2016 @ 15:15
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396939	Test Start :	01/19/2016 @ 11:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:50
Location :	105	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2396946	Test Start :	01/19/2016 @ 11:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:52
Location :	405	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:16
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396948	Test Start :	01/19/2016 @ 10:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:23
Location :	811	Received:	01/27/2016 @ 15:15
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396950	Test Start :	01/19/2016 @ 10:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:29
Location :	710	Received:	01/27/2016 @ 15:15
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.3 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2396952	Test Start :	01/19/2016 @ 09:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:16
Location :	VP Off	Received:	01/27/2016 @ 15:15
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396954	Test Start :	01/19/2016 @ 11:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:51
Location :	501	Received:	01/27/2016 @ 15:16
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 14:16
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396955	Test Start :	01/19/2016 @ 10:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:42
Location :	406-408 Cntr Rm	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396957	Test Start :	01/19/2016 @ 09:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:20
Location :	807 Store Rm	Received:	01/27/2016 @ 15:15
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396962	Test Start :	01/19/2016 @ 11:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:50
Location :	104	Received:	01/27/2016 @ 15:16
Radon Level :	0.6 pCi/L	Analyzed:	01/28/2016 @ 15:07
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2396963	Test Start :	01/19/2016 @ 10:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:27
Location :	OT Off	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: $\pm$	0.3 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2396964	Test Start :	01/19/2016 @ 10:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:30
Location :	706	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2396965	Test Start :	01/19/2016 @ 10:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:45
Location :	204	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:21
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2396971	Test Start :	01/19/2016 @ 10:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:44
Location :	206	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2396975	Test Start :	01/19/2016 @ 11:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 14:02
Location :	701	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2396976	Test Start :	01/19/2016 @ 10:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:44
Location :	505	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2398340	Test Start :	01/19/2016 @ 10:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:50
Location :	Copy Rm	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2398351	Test Start :	01/19/2016 @ 10:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:48
Location :	201	Received:	01/27/2016 @ 15:16
Radon Level :	0.5 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398394	Test Start :	01/19/2016 @ 11:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:53
Location :	404	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2398395	Test Start :	01/19/2016 @ 10:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:36
Location :	304-306 Cent	Received:	01/27/2016 @ 15:16
Radon Level :	0.8 pCi/L	Analyzed:	01/28/2016 @ 15:21
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398399	Test Start :	01/19/2016 @ 10:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:26
Location :	Gym	Received:	01/27/2016 @ 15:15
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398407	Test Start :	01/19/2016 @ 10:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:32
Location :	709	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398408	Test Start :	01/19/2016 @ 11:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:54
Location :	101	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2398409	Test Start :	01/19/2016 @ 10:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:27
Location :	OT Big	Received:	01/27/2016 @ 15:16
Radon Level :	1.0 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2398414	Test Start :	01/19/2016 @ 11:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:50
Location :	106	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398416	Test Start :	01/19/2016 @ 10:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:39
Location :	301-303 Centr	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2398417	Test Start :	01/19/2016 @ 10:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:25
Location :	Gym Stor	Received:	01/27/2016 @ 15:15
Radon Level :	0.6 pCi/L	Analyzed:	01/28/2016 @ 15:22
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398464	Test Start :	01/19/2016 @ 11:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:54
Location :	102	Received:	01/27/2016 @ 15:16
Radon Level :	0.5 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398468	Test Start :	01/19/2016 @ 09:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:17
Location :	Mail Rm	Received:	01/27/2016 @ 15:15
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 16:15
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2398472	Test Start :	01/19/2016 @ 10:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:37
Location :	Art Rm Stor	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:07
Error for Measurement is: $\pm$	0.2 pCi/L		

Canister ID# :	2398477	Test Start :	01/19/2016 @ 10:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:24
Location :	605	Received:	01/27/2016 @ 15:15
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2398480	Test Start :	01/19/2016 @ 09:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:21
Location :	Kitchen	Received:	01/27/2016 @ 15:15
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:22
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2398484	Test Start :	01/19/2016 @ 09:51
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:18
Location :	Fac Rm	Received:	01/27/2016 @ 15:15
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2398486	Test Start :	01/19/2016 @ 11:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 14:02
Location :	702	Received:	01/27/2016 @ 15:16
Radon Level :	0.7 pCi/L	Analyzed:	01/28/2016 @ 16:15
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2398488	Test Start :	01/19/2016 @ 10:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:43
Location :	504	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 15:21
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2401503	Test Start :	01/19/2016 @ 10:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:30
Location :	707	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401504	Test Start :	01/19/2016 @ 09:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:22
Location :	Lunch Rm	Received:	01/27/2016 @ 15:15
Radon Level :	0.5 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401505	Test Start :	01/19/2016 @ 10:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:41
Location :	406	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401507	Test Start :	01/19/2016 @ 11:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:50
Location :	104-106 Centr	Received:	01/27/2016 @ 15:16
Radon Level :	0.6 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401508	Test Start :	01/19/2016 @ 09:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:20
Location :	807 Store Rm	Received:	01/27/2016 @ 15:15
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401509	Test Start :	01/19/2016 @ 10:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:35
Location :	Store Rm	Received:	01/27/2016 @ 15:16
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2401511	Test Start :	01/19/2016 @ 10:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:25
Location :	606	Received:	01/27/2016 @ 15:15
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 16:14
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2401512	Test Start :	01/19/2016 @ 10:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:30
Location :	707	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 15:22
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401515	Test Start :	01/19/2016 @ 11:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 14:00
Location :	401	Received:	01/27/2016 @ 15:16
Radon Level :	0.8 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401516	Test Start :	01/19/2016 @ 10:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:38
Location :	303	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401519	Test Start :	01/19/2016 @ 09:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:22
Location :	Lunch Rm	Received:	01/27/2016 @ 15:15
Radon Level :	0.6 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401520	Test Start :	01/19/2016 @ 11:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:53
Location :	103	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.8 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2401526	Test Start :	01/19/2016 @ 10:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:29
Location :	705	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401527	Test Start :	01/19/2016 @ 10:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:35
Location :	306	Received:	01/27/2016 @ 15:16
Radon Level :	0.6 pCi/L	Analyzed:	01/28/2016 @ 15:41
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2401530	Test Start :	01/19/2016 @ 10:54
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:45
Location :	204-206 Centr	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2401531	Test Start :	01/19/2016 @ 10:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:39
Location :	302	Received:	01/27/2016 @ 15:16
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 15:07
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401534	Test Start :	01/19/2016 @ 09:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:19
Location :	807	Received:	01/27/2016 @ 15:15
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:22
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2401535	Test Start :	01/19/2016 @ 09:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:16
Location :	Main Off	Received:	01/27/2016 @ 15:15
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.2 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2401539	Test Start :	01/19/2016 @ 09:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:19
Location :	806	Received:	01/27/2016 @ 15:15
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 15:41
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2401540	Test Start :	01/19/2016 @ 10:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:39
Location :	301	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2404221	Test Start :	01/19/2016 @ 11:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:54
Location :	101	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2404224	Test Start :	01/19/2016 @ 10:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:25
Location :	606	Received:	01/27/2016 @ 15:15
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2404226	Test Start :	01/19/2016 @ 10:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:38
Location :	303	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2404233	Test Start :	01/19/2016 @ 09:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:16
Location :	Prin Off	Received:	01/27/2016 @ 15:15
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 15:07
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2404239	Test Start :	01/19/2016 @ 10:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:36
Location :	304	Received:	01/27/2016 @ 15:16
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 15:57
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2404240	Test Start :	01/19/2016 @ 10:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:45
Location :	205	Received:	01/27/2016 @ 15:16
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2404247	Test Start :	01/19/2016 @ 10:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:27
Location :	OT Front	Received:	01/27/2016 @ 15:15
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 16:29
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2404251	Test Start :	01/19/2016 @ 10:57
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:48
Location :	202	Received:	01/27/2016 @ 15:16
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 15:21
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2404253	Test Start :	01/19/2016 @ 10:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:41
Location :	407	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 15:07
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2404255	Test Start :	01/19/2016 @ 11:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:55
Location :	101-103 Cent	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:51
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2404257	Test Start :	01/19/2016 @ 10:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:49
Location :	201-203 Centr	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 16:14
Error for Measurement is:	± 0.6 pCi/L		

Canister ID# :	2404266	Test Start :	01/19/2016 @ 10:56
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:46
Location :	Lib Off	Received:	01/27/2016 @ 15:16
Radon Level :	0.5 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is:	± 0.4 pCi/L		

Canister ID# :	2404268	Test Start :	01/19/2016 @ 09:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:17
Location :	Nurses 803	Received:	01/27/2016 @ 15:15
Radon Level :	0.2 pCi/L	Analyzed:	01/28/2016 @ 16:14
Error for Measurement is:	± 0.4 pCi/L		

Canister ID# :	2404283	Test Start :	01/19/2016 @ 11:12
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:55
Location :	403	Received:	01/27/2016 @ 15:16
Radon Level :	0.3 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is:	± 0.5 pCi/L		

Canister ID# :	2404287	Test Start :	01/19/2016 @ 10:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:40
Location :	408	Received:	01/27/2016 @ 15:16
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 16:14
Error for Measurement is:	± 0.4 pCi/L		

Canister ID# :	2404303	Test Start :	01/19/2016 @ 09:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:17
Location :	803 Off	Received:	01/27/2016 @ 15:15
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:18
Error for Measurement is:	± 0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-

Individual Canister Results

Canister ID# :	2404313	Test Start :	01/19/2016 @ 09:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:20
Location :	Cust Desk	Received:	01/27/2016 @ 15:15
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 16:15
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2404314	Test Start :	01/19/2016 @ 10:57
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:48
Location :	203	Received:	01/27/2016 @ 15:16
Radon Level :	0.1 pCi/L	Analyzed:	01/28/2016 @ 14:36
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2404315	Test Start :	01/19/2016 @ 09:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	01/22/2016 @ 13:22
Location :	Stage	Received:	01/27/2016 @ 15:15
Radon Level :	0.4 pCi/L	Analyzed:	01/28/2016 @ 15:42
Error for Measurement is: $\pm$	0.4 pCi/L		

The reported results indicate that radon levels in the building tested are below the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends retesting if your living patterns change and you begin occupying a lower level of the building, such as a basement or if major remodeling is done.

General radon information may be obtained by consulting the EPA booklet: A Citizen's Guide to Radon (www.epa.gov/radon/pubs/citguide.html). To request a copy or for further information, please contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 01/27/2016

Blaine Cunningham
Webster Central School District
119 South Avenue
Webster, NY 14580-

Client: Schlegel Road Elementary School
Test Location: 1548 Schlegel Road
Webster, NY 14580-
Individual Canister Results

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201